



130 W Cochran St, Unit B  
Simi Valley, CA 93065  
Tel:818-701-4933

## Engineering Change Notification

Mar-23rd-2008

**Subject :** MCC Engineering Change Notification#080001

**Title:** GBU Series Bridge Marking Side Adjustment

**Effective date:** Apr-1<sup>st</sup>-2008(Date Code: 0814)

**Reliability Data:** N/A

**Samples contact:** [Sales@mccsemi.com](mailto:Sales@mccsemi.com)

**For question concerning this notification:** [techsupport@mccsemi.com](mailto:techsupport@mccsemi.com)

### Description and purpose :

This ECN#080001, announcing MCC has determined to adjust the Marking Side of below GBU Series Bridge Rectifiers.

Part Number:

[GBU4A-BP~GBU4M-BP](#)

[GBU6A-BP~GBU6M-BP](#)

[GBU8A-BP~GBU8M-BP](#)

[GBU10A-BP~GBU10M-BP](#)

[GBU15A-BP~GBU15M-BP](#)

Detailed difference as below: (GBU10M as an example)

Before Change	After Change
	